DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-026388 Address: 333 Burma Road **Date Inspected:** 04-Aug-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Mr. An Qing Xing **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girder (OBG)

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Chang xing Island in Shanghai, China. QA observed and/or found the following:

Vessel Zhenhua # 19,

This QA Inspector observed that ZPMC personnel were identified during Bolting on OBG Segment 14 East at various locations.

This QA Inspector observed that ZPMC personnel were identified during Bolting on OBG Segment 14 West at various locations.

This QA Inspector performed random Visual Inspection on OBG segment 14 East Internal side on panel point 125 to panel point 128 at various locations and this QA Inspector check drawing for more information. During random visual inspection this QA Inspector observed some location required welding and grinding for repair, repair area were marked by marker.

SMAW Process, Repair welding:

This QA Inspector observed ZPMC qualified welding personnel identified as Performing Shielded Metal Arc Welding (SMAW) on OBG Segment 14 West near panel point 125mm. VT repair on base metal repair area and

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

cope hole area . ZPMC QC Identified as An Qing Xing.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Shailesh	Quality Assurance Inspector
Reviewed By:	Patterson, Rodney	QA Reviewer